

LECTURE NOTES

ON

MANUFACTURING TECHNOLOGY

4th SEMESTER MECHANICAL

BY

RAJENDRA MOHANTY

LECTURER IN MECHANICAL ENGINEERING

UGMIT, RAYAGADA

Manufacturing :- It is the production of products for use or sale using labour and Machines, tools, chemical and biological processing or formulation, and is the essence of secondary industry.

Technology :- It is the sum of techniques, skills, methods and processes used in the accomplishment of objectives such as scientific investigation.

Manufacturing technology :-

It is defined as the field of study focused on process techniques or equipments, cost reduction, increase efficiency, enhanced reliability, security, safety and pollution free object.

*) Reliability :- It is the probability that a system or component will perform for a prescribed time under environment condition.

Chapter - 1 Tool Materials

Tool materials characteristics :-

(i) Hot hardness :-

→ Material must remain harder than the common work at higher operating temperature.

(ii) Wear Resistance :-

→ The material must resist relative hardness of workpiece or any changes.

(iii) Toughness :-

→ It is a common/combination of strength and ductility. It must have sufficient toughness to prevent vibration and ~~breakage~~ breakage.

(iv) Cost of fabrication :-

→ It should have reasonable (Low).

→ It should have low cost within limits.

Ductility :- It is the physical property of a material associated with the ability to be hammered thin or stretched into wire without breaking. A ductile substance can be drawing into a wire.

Malleability :- It is the physical property of

Metals that defined their ability to be hammered, pressed, or rolled into thin sheet without breaking.

Date - 14/12/2019

Composition of Tool Material :-

Tool Material types are Cutting tool :-

(i) Carbon Steel :-

Composition : The carbon amount range from 0.008 - 1.5%

(ii) Medium Alloy Steel :-

Composition :- It have a carbon contain same as plain carbon steel or mild steel in addition 5% Alloy of tungsten (W), Molybdenum (Mo), Chromium (Cr), Vanadium (V).

(iii) High Speed Steel (H.S.S) :-

High tungsten :- (18-4-1) (T-Series)

Tungsten - 18%

Chromium - 4%

Vanadium - 1%

High Molybdenum (6-6-4-2) (M-series)

Molybdenum - 6%

Tungsten - 6%

Chromium - 4%

Vanadium - 2%

High Cobalt :- (C-series)

It is called as "super High Speed Steel".

Cobalt added 2-15%

Tungsten - 20%

Chromium - 4%

vanadium - 2%

(iv) Satelites :-

It is a non-ferrous Alloy

Cobalt = 40-48%

Chromium = 30-35%

Tungsten = 12-19%

(v) Cemented Carbide :-

82% Tungsten carbide

10% Titanium Carbide

8x Cobalt

vi) Ceramics :-

- Generally use aluminium oxide
- It is made by composing AlO_2 powder in a mold about 260 kg/cm^2

vii) ~~Ceramic~~ Diamond :-

- These are naturally occurring diamond or carbon compounds.
- Composition of abrasive.
- It is mainly used for grinding harder material where superior finishing required.

Task:

* What is duplex steel?

- Duplex stainless steels are family of stainless steels. These are called duplex grades because their metallurgical structure consist of two phases, austenite and ferrite in roughly equal proportion.

* What are ceramics and abrasive?

Ceramics :- A ceramic is an inorganic non-metallic solid made up of either

metal ore non-metal Compounds that have been shaped and then hardened by heating to high temperature.

Abrasive :- An Abrasive is a material, often a mineral, i.e. used to shape or finish a workpiece through rubbing which leads to parts of the workpiece being worn away by friction.

Ex: - wood, sandpapers, sand

(iii) Hydraulic Energy to Mechanical Energy

Water turbines :- Convert hydraulic Energy to Mechanical Energy is used to drive generators that develop electricity. Water turbines are generally designed and manufactured to each power stations own conditions of water head, discharge, water and power demands.

(iv) A.c to D.c

A rectifier is an electrical device that converts A.c to D.c.

(v) Electrical Energy to Mechanical Energy

A motor generates or converts Electrical to Mechanical Energy.

Mechanical Energy to Electrical Energy

A generator converts Mechanical to Electrical Energy.

(vii) (C.B.N) Cubic Boron nitride

→ It contains atoms of boron and nitride.

→ It is the hardest tool material.

* Physical properties and uses of different type of tool material.

The various type of tool materials are

(i) Carbon steel

(ii) medium ^{alloy} steel

(iii) high speed steel

(iv) cast alloy steels

(v) Cemented Carbide tool material

(vi) Oxide or Ceramic tool material

(vii) Diamonds

(viii) Abrasives

(ix) Cubic boron nitride (CBN)

1. Carbon steel :-

Properties

→ Low hot hardness

→ poor hardenability

→ Can be with stand cutting temperature 200°C

→ Carbon tool steel are harder than many hss.

uses :-

It can be used most economically under the condition.

→ The carbon steel are used for making certain taps and drills.

→ for making wood working tools.

2. Medium Alloy steel :-

Properties :-

→ Better hardenability

→ higher wear resistance

→ higher hardness

uses :-

→ used for making drills.

→ used for making taps, etc.

→ It can cut effectively up to temperature 250° to 300°C .

3. High Speed Steel :- (H.S.S.)

Properties :-

→ High hot hardness

→ cutting tool retain the cutting ability up to 600°C

→ High wear resistance

→ The hardenability is good.

uses :-

→ Drills.

→ Broaches

→ Milling cutters

→ Lathe cutting tools.

→ Taps, etc.

4. Cast alloy Satellite :-

Properties :-

- (i) Material is not so hard of at room temperature.
- (ii) hardness above 1000°f is greater than H.S.S.
- (iii) Hot hardness is higher than H.S.S at higher temperature.
- (iv) This material is very brittle.

uses :-

These materials are used extensively in some non metal cutting application such as rubber, plastic.

(v) Cemented Carbide :-

properties :-

- High hardness
- high heat resistance
- high wear resistance
- high hot hardness up to a temperature of 900°C .
- Low specific heat

uses :-

These tool materials are used for machining cast iron, alloy steels.

(6) Oxides Ceramic Tool Material :-

properties :-

- (i) The ceramic has extremely high compressive strength. It is quite brittle.
- (ii) Heat conductivity is very low. So generally no coolant is required while machining.
- (iii) The ceramic tools can retain strength and hardness up to 1000°C

uses :-

These tool materials are used for turning, boring, etc operations at high speed.

(7) Diamonds :-

properties :-

- (i) It has low coefficient of friction.
- (ii) Hardness of the diamond is incomparable.

uses :- Diamonds are suitable cutting very hard material such as glass, plastics.

Ceramics.


Abrasive :-

uses :-

For most grinding operations there are two kind of abrasives in general use namely aluminium oxide and silicon carbide. The aluminium oxide abrasive are used for grinding all high tensile materials, whereas silicon carbide abrasive are more stable for low tensile materials.

Cutting tool:-

- (i) Any tool which can be used to remove material from workpiece.
- (ii) Tool must be harder than the work piece and it must contain specific geometry and clearance angle.



(Picture of orthogonal and oblique cutting)

Single point cutting tool:-

Rake angle:- It is the angle between front of cutting face to perpendicular line to workpiece.

Single point cutting edge :-

These have only one cutting edge used in length, Shaper, planer, boring machine.

Multi point cutting edge :-

These have more than one cutting edge or multiple cutting edge (ex-drill).

Task :-

Shaper :-



A shaper is a type of machine tool that uses linear relative motion between the workpiece and a single-point cutting tool to machine a linear tool path.

Planer :-

A planer is a type of metal working machine tool that uses linear relative motion between the workpiece and a single-point cutting tool to cut the workpiece.

Slitter :-

It moves smoothly over a surface with a twisting or oscillating motion.



Picture of cutting forces in conventional turning process.

Cutting Action of hand tool :- Dt-04/01/20


Chisel :-

- (i) It is a cutting tool and a attached blade on its end. It is used for carving cutting hard materials like wood, stone, metal.
- (ii) It is forced in material linear to relative motion.
- (iii) The driving force manually applied using hammer.
- (iv) It is used in wood working and metal working operations like carving, cutting, shaving, shaping trimming.

Types of working on chisel :-

- (i) Cold chisel
- (ii) Hot chisel

Cold chisel :-




- (i) It is made from tempered steel.
- (ii) used to cut cold material.
- (iii) used for rough finishing.

Hot chisel :-

- (i) It is used to cut materials at high temperature (heated metal)
- (ii) used for smooth finishing

Hacksaw Blade :-




- (i) It is a fine tooth saw. It can cut plastic, wood, and other non-metals.
- (ii) It is attached to 'C' shaped frame which holds blade under tension.
- (iii) The frame can be adjustable.
- (iv) Blades are available in standardised length of 10" or 12" for standard Hacksaw.
- (v) The pitch of the teeth 14-32 per inch.
- (vi) It is set in a wave. It is made of Carbon steel or mild steel.

Die :-

- (i) It is used for low strength material such as Rubber, cloth, plastic, Sheet metal etc.
- (ii) It can be done on flat bed or rotary process.

- (iii) For rotary dry cutting used cylindrical die.
- (iv) It is used to cut External thread on rod or pipe.
- (v) It is made up of H.S.S (High speed steel)
- (vi) This process is called dieing.
- (vii) This process can be controlled by electric, hydraulic and pressurised.



(Rake Angle on a die)

Reamer :-

- i) It is a multiple edge cutting tool the process of enlarging hole is called reaming.
- ii) It consists of helical cutting edge.
- iii) It is used to remove small amount of material and it is made of high carbon or plain carbon steel.

Machining process parameter :-

Factors affecting tool life :-

* Cutting Speed :-

It can be defined as relative surface speed between tool at the job or amount of length that will pass the cutting edge of tool per unit time.

* Feed :-

It is defined as relation by small movement per cycle of cutting tool relative to the workpiece usually, along the cutting speed direction.

* Depth of cut :- (D.O.C)

- It is the thickness of the layer of metal removed in one cut or pass.
- Initial - final.

vii) Colourless and orderless

viii) harmless to bearing

ix) harmless to skin

x) non-corrosive

xi) Transparency

xii) low viscosity

xiii) low price.

Choice of cutting fluids:-

- 1) Type of operation
- 2) The rate of material removed
- 3) material of the workpiece.
- 4) material of the tool
- 5) Surface finish requirements.
- 6) Cost of cutting fluids.

* TIME of cutting fluids:-

Water:-

pure water is the best cutting fluid available because of highest heat carrying capacity but, water creates corrosion.

* Coolants & lubricants :-

These are the liquid or gases applied to tool and workpiece to assist cutting operations (friction, heat, and gases flying chips).

* Purpose of lubricants :-

- i) To cool the tool.
- ii) To cool the work piece.
- iii) To lubricate and reduce friction.
- iv) To improve surface finish.
- v) protect from corrosion.
- vi) Break chips into small parts.
- vii) To wash the chips away from the tool.

* Properties of cutting fluids :-

- i) High High absorption
- ii) Good lubrication
- iii) low co-efficient of friction
- iv) High flash point.
- v) stability not to oxide
- vi) Neutral in nature (chemically not create)

- vii) Colourless and orderless
- viii) harmless to bearing
- ix) harmless to skin
- x) Non - Corrosive
- xi) Transparency
- xii) Low viscosity
- xiii) Low price.

Choice of cutting fluids :-

- 1) Type of operation
 - 2) The rate of material removed
 - 3) material of the workpiece
 - 4) material of the tool
 - 5) Surface finish requirements.
 - 6) Cost of cutting fluids.
- * TIME of cutting fluids :-

Water :-

Pure water is the best cutting fluid available because of highest heat carrying capacity but, water creates corrosion.

Soluble oil :-

- These are made of 80% of water, soap and mineral oil.
- The soap break oil into minor particle to dispose through water.
- Water increase cooling, and oil provide lubrication.

* Straight oils :- (fatty oils)

The straight oils may be

- i) straight mineral oils, kerosene, petrol.
- ii) It consist of animal, vegetable or synthetic equivalent, lard oil etc.
- iii) It has both cooling and lubricating property.

* Mixed oils :-

- i) It is a combination of mineral

*) Cutting tool Geometry :-

SHANK :- It is main body of the tool.

FLANK :- Surface below and adjacent to the edge.

Heel :-

It is the intersection of flank and base of the tool.

Nose :-

It is the point where the side cutting edge and end cutting edge intersects.

Cutting edge :-

It is the face of the tool which remove the material from workpiece. It consists of measure, minor and nose.

Face :- The face surface against which the chisel slides upwards.

Base :-

It is the underside of the SHANK.

Rake :-

It is the slope away from the cutting edge. Larger than rake angle more the cutting surface.

(i) Negative it slope is reversed.

Side rake Angle :-

It is the Angle between tool face & line parallel to base. Measure perpendicular.

(i) Negative is slope is towards cutting tools.

(ii) Positive is type away from the cutting edge.

Perpendicular.

- (i) The Angle is positive in cutting edge shape downward.
- (ii) Negative if slope is reversed.

Side rake Angle :-

It is the Angle between tool face & line parallel to base measure perpendicular.

- (i) Negative if slope is towards cutting tools.
- (ii) Positive if type away from the cutting edge.

CH-3 LATHE MACHINE

Lathe machine :-

It one of oldest machine used for rotating & machining pitch of work. its function is to move metal from work piece of required shape & size.

Type of Lathe :-

1. Speed Lathe :-

Wood working, Sintering, polishing, & spinning.

2. Engine Lathe :-

Belt drive, motor drive, gear head lathe.

3. Bench Lathe :-

Tool room Lathe, Capstan & turret Lathe

4. Special purpose Lathe :-

Wheel Lathe, Bed Lathe

parts of Lathe :-

Bed :-

(i) The bed is the base and foundation of the lathe.

(ii) It is made of cast iron.

(iii) It is massive and rigid casting made in one piece to resist deflection & vibration.

- Its Support head stock, tail stock carriage.

Head Stocks :-

- (i) It is an assembly permanently fastened to the left end of the lathe.
- (ii) It provides Rotation of work area multiple speed.
- (iii) It is made of carbon or Nickel Chrome steel.
- (iv) It contain Gear box, Chuck, face plate Spindle.
- (v) Spindle is follow through out the length through which long bar can be feed.

Tail stocks :-

- (i) Located in opposite way in right side of head.
- (ii) It is a non-rotating part with slide and clamp.
- (iii) It accommodate or allow different length work pieces.

Uses :- Support other end of work when machined between do centered.

- (iii) Hold the tool for drilling, reaming & tapping.

Carriage :-

It is placed in between Head stock & Tail Stocks.

→ It is movable & hold cutting tool to impart longitudinal cross speed.

parts of carriage :-

① Saddle :-

It is an shape casting that feeds over head & it carriage cross slide & tool post.

② Cross Slide :-

It is mounted on saddle it provides cutting tool motion can be moved by feed screw controlled by wheel or by power feed.

③ Compound Rest :-

It is mounted top of cross-slide & support tool post it can be moved by screw and hand wheel not by power feed.

④ Tool post :-

It is mounted top of compound rest and it can be moved and clamped in any position. it can rotate and hold the cutter at any desired angle.

⑤ Apron :-

The portion of a the carriage which extend in front of the lathe which contain gears.

Clutch lever it also contain friction clutch.

③ Feed Mechanism :-

Longitudinal feed cross feed & Angular feed.

④ Lathe operations :-

Turning, chamfering, threading, cutting, facing, knurling, parting, grooving.

Facing :- it generate flat surface perpendicular to rotational axis. The tool feed into workpiece spindle speed selected and the tool feed by hand and feed given by cross-slide.

Turning :- it remove excess material from workpiece.

① Straight turning :-

It produce cylindrical shape.

② Rough turning :- Remove of excess material by applying high rate of feed & depth (2-2-5 mm) and feed rate 0.30 - 1.5 mm.

③ Taper turning :-

① Uniformly increase or decrease in diameter.

② It produce conical surface.

(a) Knurling :-

- (i) It is the process of marking a diamond shape pattern or a zigzag pattern on surface workpiece.
- (ii) It help to provide grips and prevent from slipping it uses special knurling tool set up. Steel rollers with a holder.

Parting OFF :-

It is the operation of cutting workpiece after machine to required shape & size.

$$\tan \theta = \frac{D-d}{2L}$$

Threading Cutting :-

- It is similar to cutting operation where boring tool with cutting edge used to create thread.
- The tool is fixed on tool post and Angle feed through lathe.
- The components as per given data of lathe.

Internal Machining :-

① Drilling :-

- (i) Production of cylindrical hole by rotating cutting edge called drill.
- (ii) Work piece revolve is chuck on Face plate and drill head in tail stock.
- (iii) Feed affected by movement of tailstock.

② Boring :-

- It is the operation of enlarging of hole by drilling, punching and forging.
- The work clamped in carriage & the boring bar hold the tool.
- The work clamped is carriage & the boring bar holds the tools.
- Longitudinal movement gives feed.

Safety measure during machining :-

- (i) before operating one should feel organized how to run and stop.
- (ii) Safety goggles preferred.
- (iii) above raincoats let clutch.
- (iv) Sufficient distance mentioning tools and instru-

Capstan & Turret

- ① The head stock possess is wider range of speeds and the in construction require 15 HP power to drive the spindle.
- ② The tool post mounted on the cross slide is four ways & a near tool post is mounted on the near slide which holds 4 tools.
- ③ In turret lathe, the tail stock is replaced by a turret by a turret which is hexagonal block which contain is 6 tools on each face.
- ④ The feed movement of each tool set on square of hexagonal turret is Regularity by stops & feed strips.
- ⑤ Combination cuts can be taken by mounting two or more tools on the sides on the same face of turret.
- ⑥ The labour cost is less.
- ⑦ The threads are cut by die heads & taps.
- ⑧ Turret lathe are suitable for producing large no of identical pieces.

Engine Lathe

- (i) It requires 3 hp drive the spindle.
- (ii) In Engine lathe, one tool can be mounted at one time for different operations.
- (iii) It can accommodate one tool of limited size.
- (iv) The feed movement is given by hand.
- (v) Combination cuts can not be done.
- (vi) Labour cost is more.
- (vii) The threads are cut by lead screws. Centre lathe is suitable for odd jobs having different shapes & sizes.
- (viii) The threads are not cut by lead screws.

Capstan Lathe

Turret lathe

- (i) Its turret head is mounted in slide which moves on the Guide ways produced on the saddle.
 - (ii) For feeding the tool to the work the saddle is fixed at convenient distance from the work.
 - (iii) It is suitable for smaller size & lighter jobs it is not suitable for heavy cutting condition.
 - (iv) It is suitable to work the smaller bar up to 60mm dia.
 - (v) The turret head may be hexagonal or circular.
 - (vi) It is smaller in size compared to turret lathe.
 - (vii) The tool traverse is faster and offers less fatigue to the hands of the operator.
- (i) It is turret to head is mounted directly on the saddle.
 - (ii) For feeding the tool to the work, the entire saddle unit is moved.
 - (iii) It is suitable for long and heavy work and severe cutting conditions.
 - (iv) It used to work for large size bar up to 200mm dia.
 - (v) Turret head is hexagonal.
 - (vi) It is large in size compared to capstan lathe.
 - (vii) The tool feeding is retracted slower and provide more fatigue to operation hands.

Production of Hexagonal Bolts :-

<u>Operation No</u>	<u>Description of operation</u>	<u>Tool position</u>	<u>Tools</u>
01	Hold in Collect	1 st Turret position	Bar stock
02	Turn to 16 mm dia	2 nd Turret position	Roller steady bar turning tools.
03	Form end of Bolt	3 rd Turret position	Roller steady bar ending tool.
04	Screw 16 mm	4 th turret position	slit opening dia head with chas 16 mm
05	Chamfer	front cross - Slide tool post	Chamfering tools
06	Parting off	near tool post	Parting off tool.

1. Chuck
2. Tool post
3. Chamfering tool
4. Reamer
5. Second drill
6. First drill
7. drill & counter sink
8. Work stock
9. Four Station turret

(a) Setting of Bar stock :-

It is said at a distance 70mm from the collect by using slip gauge extra length of 10mm bolt length allowed 4mm parting of 6mm if clearance.

(b) Setting of Roller steady turning tool :-

- (i) The turning tool set turret face for diameter 16mm. the stop tool is 20mm
- (ii) The rollers are set behind cutting edge at 1.5 mm

B) Setting Roller bar ending tools :-
The ending set on turret face brought
operation after turning process.

D) Setting self opening dia head :-
It is mounted turret face and dia sure
fitted to cut thread 16mm diameter.

E) Setting chamfering tools :-
It is mounted 4 station turret on
cross slide and extreme longitude position
of the saddle adjusted.

B) Setting of parting off tools :-

This set on readdy tool post and the longitudinal position parting off at distance 4mm of from furthest face.

Internal Machining :-

Tapper Drilling :-

D = large diameter of tapper

d = small diameter of tapper

L_1 = Length of work

L = Length of the tapper

$d = \text{half taper angle}$

$S = \text{set over}$

CH-4 SHAPER MACHINE

DI-10/02/2020

Shaper Machine :-

- It is Reciprocating dia of machine tool used to produce.
- Flat surfaces the surface may be horizontal, vertically or incline.

Working Principle :-

- ① The job are fixed rigidly in vise clamped to machine table and the tool held in tool post mounted the Ram.
- ② The Ram moves and force motion and max the tool to cut material in forwards stocks.
- ③ No cutting task places running return ideal stock stocks the job is given feed in a direction normal to the cutting tool actions.

Types of Shaper :-

- ① According to Mechanism 3 types
 - Ⓐ Crank types
 - Ⓑ gear types
 - Ⓒ horidlic types
- ② According position and travel of Ram
 - Ⓐ horizontal type

- b) vertical types
- c) head travelling types
- ③ According to design of table
 - Ⓐ stand shaper
 - Ⓑ inverts shaper
- ④ According to cutting strokes -
 - Ⓐ push types
 - Ⓑ draw types

Specification of Shaper Machine :-

- ① maximum length stroke - 175mm to 900mm.
- ② maximum horizontal travel
- ③ maximum vertical travel
- ④ maximum distance from table to Ram.
- ⑤ tool box with vertical adjustment.
- ⑥ Length on work table
- ⑦ Different Range of speed and available
- ⑧ Different Range of feed available

Parts of Shaper Machine :-

Base :-

The Base provided stability as it support equipments of shaper and observe force and vibration it is made cast iron.

Column :-

→ Column is hole casting and mounted on base it provided.

→ Ram driving Mechanism necessary guide ways provided way linear movement of the Ram.

Cross Rail :-

(i) It is mounted on front vertical guide ways, to of Column.

(ii) It has two parallel guide on its top vertical plane perpendicular to Ram axis.

Saddle :-

(i) It is mounted on cross rail which hold the table.

(ii) The cross wise movement of the table control by feed screw.

Table :-

→ The table fastened into column and provided L7' slot for mounting work piece.

- ② The table can moved open down and cross wise.

Ram:-

- ① It is Reciprocating member and semic cylindrical shaper.
- ② It is full rigid inside and a single point cutting tool attach tool.

Tool head:-

Single point cutting tool used. The tool head hold the tool provide vertical and Angular feed and provided automatic relief during return stroke.

Shaper - Mechanism:-

- ④ Crank and slotted Mechanism:-

① PMM & PMR Tangent to the crank pin circle.

② When the link is PM

(i) $\overset{\wedge}{CEB}$ = Cutting Stroke
 $\overset{\wedge}{BDC}$ = Return Stroke

$$\frac{CEB}{BDC} = \frac{\alpha}{\beta} = \frac{\alpha}{360^\circ - \alpha}$$

- | | |
|-------------------|-------------------|
| 1. Knob | 5. Wheel |
| 2. Pin | 6. Arm Fulcrum |
| 3. Helical Spring | 7. Connecting Pin |
| 4. Pawl | 8. Driving disc |
| | 9. Crank Pin |

1. The Arm pivoting about screw around Connecting Rod and Carriage Spring loaded pawl.
2. It helps in power feed to operated forward and reverse directions.
3. Direction can be provided by varying the distance between Centre and disc.
4. Large the side greater the feed and v.
5. The Amount feed depend on type of finish. The disc carry a spur gear driven bull gear. It cause the Connecting Rod to Reciprocated and it moves the pawl over one or more teeth.

Applications of Shaper Machine :-

- ① To generate straight and flat surface.
- ② Smooth re-entrant surface.
- ③ To make gear teeth.
- ④ Machine dies, punches and slides.

CH-5 PLANNER MACHINE

Planner Machine :-

It is a Machine which produce plane flat surface by single point cutting tool.

Shaper Machine

(i) It used for small workings (ii) It used for large workings.

(iii) Single point cutting tool used (iv) To Extra cutting used for Machining.

(v) Cutting tool moves up, down (vi) Cutting tool remain in horizontal directions. motionless.

(vii) Stroke length is small (viii) Stroke length is bigger

(ix) Cutting Rate and Cutting Stroke differ (x) It has stable cutting Speed.

(xi) Work piece held tightly on Bed. (xii) Work piece held firmly on a horizontal moving table.

* Parts of a Planner :-

BED :-

→ The bed of a planner is a box like casting cross ribs.

→ It is a very large in size and heavy in weight and it supports the column and all other moving parts of the machine.

→ The Guided ways provided on the bed for the movement of the table.

The hollow space within the box like structure of the bed home the driving mechanism for the table.

Table :-

The table supports the job and reciprocates along the ways of the bed.

The planer table is heavy rectangular casting and is made of cast iron.

The top face of the table is accurately finished in order to hold the job correctly.

The top face of the table is "T" slotted for clamping the job and job holding devices.

At each end of the table or hollow space is left for collecting chips.

A groove is cut on the side of the table for clamping planer reversing dogs at different position.

Column :-

- It is a rigid vertical box like structure.
- The front face of each housing is accurately machined to provide guide ways on which the carriage may be slipped up and down for accommodating the different suitable

Heights Job.

The housing is enclosed with vertical elevating screw and cross feed screws for tool heads and counter balanced the weight of the cross rail.

Cross Rail :-

- It is a rigid box like casting connecting the two housings.
- The cross rail can be raised or lowered on the face of the housing and can be clamped at any desired position.
- The cross rail when clamped should remain parallel to the top surface of the table.
- The two elevating screws in two the housing are rotated by an equal horizontal any in position.
- The two tool heads are mounted upon the cross rail.
- The cross rail has screws for vertical and cross feed of the tool heads and a screw for elevating the rail.

Tool head :-

- The tool head of the planner is similar to that of a shaper in construction and operation.

Clamping of job :-

- There are three important points to be noted while clamping the job on the planer table.
- Proper clamping should be done all around the job.
- The job should be held such that the surface planned should remain in proper position with other surface.
- The job may be located on the planning machine table by the following methods.
- By standard clamping devices.
- By special fixtures.
- The standard clamping devices are stops, planer jacks, heavy duty vises, plates & planer centres etc.

* PLANNER TOOLS :-

- The cutting tools which are used in planer are single point cutting tool which are used in lathe and shaper.
- Planer tool may be solid forged type bit type.

- The bit may be brazed, welded or mechanically fixed on a M.S. bar.
- As a planer tool has to take up heavy cuts, the tools are made heavier and larger in cross-section.

Milling Machine :-

6th lesson

- A Milling Machine is a type of metal cutting device which remove metal with a fast rotating multi-tooth cutter.
- This Machine yield high production of different varieties of jobs, in choice for production Machine.
- Smaller jobs are employed for machining in Milling M/c.
- Using multi tooth cutters & various forms of cutter, A Milling Machine can be economically employed for generating varieties of surface quite speedily.

Types of Milling Machine :-

- (a) Column and knee type :-
 - Hand Milling
 - Plane Milling
 - Universal
 - Vertical
- (b) Fixed belt type Milling
- (c) Planer type Milling

iv) Special type milling M/c.

Rotary table M/c

Deep milling machine

Milling attachment :-

- It is a rotary table types work holding device bolted on the table.
- It provides a rotary motion to the work-piece in addition to longitudinal, cross & vertical motions.

Work Holding devices :-

- Angle plates.
- V-blocks
- Special fixtures.

Dividing head :-

They are 3 types

- ① Plane or simply indexing head (imp)
- ② universal dividing head (V.I.M.P)
- ③ optical dividing head.

Plane indexing head :-

- It has a spindle which carries job holding

device such as jaw, chuck, face blade and centre carries.

- A worm rigidly fixed on spindle which crank is mounted on worm shaft such that the rotation result in rotation of spindle.
- In a plane dividing head spindle rotates only on horizontal axis.
- The index plate remain constant as fixed.
- The amount of spindle relative to work depend on ratio between worm and worm wheel.
- The most common ratio is $40 : 1$
i.e. = 40 revolution of index crank as worm wheel move the spindle one revolution.

universal dividing head :-

- It is most commonly used type of attachment in milling machine.
- It is used for setting the work piece in horizontal vertical and inclined position relative to milling machine table.

- Turning the work periodically from indexing
- A continuous rotary motion creates helical gear in milling operation.
- The dividing head connected to table feed screw through a gear train to impart a continuous rotary motion.
- Its working mechanism is the crank rigidly fixed at one end while the vernier runs feed.
- The index plate is bolted with gear and can be locked against rotation of lock pin.

Optical Dividing head :-

- It is used for high precision angular indexing with respective milling cutters the reading built into dividing head for optical system.

Work Holding Attachments :-

Special Attachments use on milling machine

- Vertical Milling attachments
It is used for horizontal spindle to do facing on horizontal surface
- Universal milling attachment :-

Similar to vertical attachment with ^{Accidentally} the spindle about two mutual perpendicular axes.

Direct Index :-

It has an index placed fitted directly on spindle.

The intermediate use of work while is avoided.

The index plate has 24 holes and use index fixture

Compound

It uses two different circles of one plate.

It rotate the crank or the handle by

Differential Index :-

A set of gears placed at extra in between plates.

It is connected to gear train, which receive motion from worm wheel.

$$\frac{\text{Driver}}{\text{Driven}} = \frac{(n-N) 14}{11}$$

N is the no. of Division

$(n-N)$ if positive the index plate rotate has with crank.

If $(n-N)$ is negative it rotates opposite of crank. If negative

Chapter-7 Slotter MACHINE

Slotter Machine :-

- It is use fore cutting grooves, key ways and slots of
- It make regular, irregular surface both by internal and external machining.
- The ram reciprocates in vertical axis.

Machine parts :-

Base/Bed :- It is rigidly build to with stand all cutting forces and entire load of the machine.

Column :- It is vertical member and can't integral with the base.

- Driving Mechanism & feeding Mechanism inside the Column.
- The front vertical face accurately finished for providing ways to ram.

Saddle :-

- It is mounted on guideways and reciprocate from the Column by power or manual control it provide longitudinal feed.
- The top surface of the saddle is accurately finished to provide ways to the Cross-Slide.

Cross-Slide :-

It is mounted upon the Guideway and move parallel to the column. It is controlled by power feed etc.

Rotating table :-

It is a circular table mounted on cross slide. The table rotate in degrees by rotating ~~indexing~~ indexing.

T-slots are cut top face of the table for holding different Clamp Device.

Ram :-

It is Reciprocating member of the machine mounted on the column.

It supports the tool at it's bottom end on toolhead.

Ram drive Mechanism :-

A slotter removes metal during downward cutting stroke and the upward is ideal stroke.

It reduce the ideal time and quick return mechanism applied in the machine.

Feed Mechanism :-

The feed is given by table.

It has 3 types of moment.

① Longitudinal :-

It is the table feed is perpendicular to the column toward or away from face. it is called longitudinal.

② Cross-feed :-

If the table feed is parallel to the face of column it is called cross-feed.

③ Circular feed :- It is the table rotated in vertical axis the feed motion is circular feed.

Slotting Tools :-

α = Top Rake Angle

β = Clearance Angle

- In slotting the angles are provided for better cutting and it acts along the length of the tool.
- The nose of the tool slightly behind the shank.
- The slotting tools are forged type.
- Bit type tools fitted in heavy duty tool holdings.

Keyway cutting tools are thinner cutting edges.

- round nose tools use for machining circular surface.
- Square nose tools are use for machining flat surface.

- It is the process of removing material from work piece.
- It brings the diameter very close tolerance (0.02mm) limits or give a fine finish.
- The grinding machine support and rotates grinding wheel for smooth operations.
- It remove very small amount chips.

Methods of Grinding :-

According to type surface to be grounded main kinds of grinding method are

- (i) External cylindrical grinding
- (ii) Internal cylindrical grinding

External cylindrical grinding :-

- It produce a straight or tapered surface on a work piece.
- It is a rotate a about its own axis between centres.

Internal cylindrical grinding :-

- (i) It produce internal cylindrical holes & tapers
- (ii) The work is chocked and rotated on its axis, and the grinding wheel rotate against the wheel.

Types of grinding :-

(1) Surface Grinding :-

It produce flat surface and work may be grounded by grinding wheel.

(2) Face grinding :-

It is a method of grinding vertical flat surface and the spindle wheel may be horizontal or vertical.

(3) Form grinding :-

It is done by specially shaped grinding wheels to make gear teeth, thread, shaft, etc.

(4) Set Wheel Grinding :-

It is a method of grinding short workpiece without changing grinding wheel.

(5) Centre. less Grinding :-

It is a method of grinding external

- It is the process of removing material from work piece.
- It brings the diameter very close tolerance (0.02 mm) limits or give a fine finish.
- The grinding machine support and rotates grinding wheel for smooth operations.
- It remove very small amount chips.

Methods of Grinding :-

According to type surface to be grounded

Main kinds of grinding method are

- (i) External cylindrical grinding
- (ii) Internal cylindrical grinding

External cylindrical grinding :-

- It produce a straight or tapered surface on a work piece.
- It is a rotate a about its own axis between centres.

Internal cylindrical grinding :-

- (i) It produce internal cylindrical holes & tappers
- (ii) The work is chocked and rotated on its axis, and the grinding wheel rotate against the wheel.

Types of grinding :-

(1) Surface Grinding :-

It produce flat surface and work may be grounded by grinding wheel.

(2) Face grinding :-

It is a method of grinding vertical flat surface and the spindle wheel may be horizontal or vertical.

(3) Form grinding :-

It is done by specially shaped grinding wheels to make gear teeth, thread, shaft, etc.

(4) Set wheel grinding :-

It is a method of grinding short workpiece without changing grinding wheel.

(5) Centre less grinding :-

It is a method of grinding external

of internal cylindrical surface in which the work is supported against a regulating wheel, a grinding wheel.

(B) OFF hand Grinding :-

It is a rough grinding method in which work is held in hand pressed against the rotating wheel.

Types of Grinding Machine :-

- Surface Grinder
- Cylindrical Grinder
- Centre less Grinder
- Portable Grinder
- Pedestal Grinder
- Cutter & tool Grinder
- Internal Grinder
- flexible shaft Grinder

Chapter - 9 Internal Machining Operations

Introduction of drilling Machine :-

→ In a drilling machine holes may be drilled quickly and at a cost.

→ The hole is generated by the rotating edge of a cutting tool known as "drill bit" which exerts large force on the work clamped on the table.

Classification of drilling Machines :-

- Bench drilling machine
- Pillare drilling machine
- Radial drilling machine

Bench drilling Machine :-

→ The Bench drilling machine is a small machine for drilling a small holes at high speed in light jobs. It is also called as "Sensitive drilling machine".

→ The drill is fed into the work by purely hand control.

→ This machines are capable of rotating drills of diameter from 1.5 to 15.5 mm.

Working of Bench drilling Machine :-

→ Work piece with the exact location marked on it with the centre punch is clamped rigidly on the work table.

→ Spindle axis and centre punch indentation are in same line.

→ Machine is started and drill bit is lowered by rotating feed handle.

→ Drill bit touches the work and starts removing material.

Pillar drilling Machine :-

- Pillar drilling machine is free standing and is of a far heavier construction able to take larger drills.
- It has a heavy frame to support a wide range of work.
- The table height is adjustable and power speed and feeds are available.
- The larger drills normally have a taper shank located within taper bore in the spindle end.

These tapers are standardized as Morse tapers.

Radial Drilling Machine :-

→ These are heavy duty and versatile ~~drilling~~ ~~machine~~ drilling machine used to perform drilling operations on large and heavy work piece.

→ Holes up to 7.5 cm.

Working of Radial Drilling Machine :-

→ Workpiece is marked for exact location and mounted on the work table.


→ Drill bit is located by moving the radial arm and drill to the marked location.

→ By starting drill spindle motor holes are drilled.

* Boring :-

→ Lathe boring is a cutting operation that uses a single-point cutting tool or a boring head to produce one cylindrical surfaces by enlarging an existing opening in a workpiece.

→ The cutting tool moves parallel to the axis of rotation.




(Boring)

* Broaching :-

→ Broaching is a machining process that uses a toothed tool, called a broach, to remove material.

→ Broaching is a similar technique to shaping with a long multiple-tooth cutter.



(Broaching Operation)

Types of Broaching :-

Broaching's are two types :-

(1) Pull type

(2) Push type

Pull broaching :-

Workpiece is clamped to the broaching machine in stationary position and the broach is pulled through the work.

Broaches are usually long and are held in a special head. Pull broaching is mostly used for internal broaching.

(Q) Push broaching :-

→ Workpiece is held in the broaching Machine in stationary position and broach is pushed through the portion of workpiece to the Machine.

→ Push broaching is done by hand and airbor Presses (hydraulic press).

→ This method is also use for internal broaching like for sizing and finishing the holes, Cavities, and key ways.

Applications of broaching :-

(i) High production rate.

(ii) Job is prepared in one stroke.

(iii) High tool life

(iv) Internal & External Machining can be done

(v) 0.8 micron finishing can be obtained.

(vi) Interchangeability of components can be done due to tolerances obtained in range.

(vii) Roughing & finishing can be done in single stroke.

* Applications of braehing :-

- Automotive
- Agriculture
- Industrial Manufacturing
- Oil & gas
- heavy equipment
- fasteners & gears

Drilling

- Drilling is performed to originate a hole.
- Cutting tool used for drilling is known as drill.
- Drill is a double point cutting tool.
- Drilling is the first phase of hole fabrication. It doesn't require any special feature prior to operation.
- Drilling can increase the length of the hole.
- Surface quality of drilled hole is not very good.
- Material removal rate (MRR) in drilling operation is higher.

Boring

- Boring is performed to enlarge the diameter of an existing hole.
- Cutting tool used for boring is known as boring bar.
- Boring bar is a single point cutting.
- A pre-drilled hole is mandatory for performing boring.
- Boring can increase diameter of an existing hole.
- Surface quality is better than drilling.
- MRR is lower than drilling but higher than reaming.

Reaming

- Reaming is performed to finish hole surfaces and to improve tolerance.
- Cutting tool used for reaming is called reamer.
- Reamer is a multi-point cutting tool.
- Similar to boring, reaming can be performed only if a hollow part or hole exists.
- Neither diameter nor length can be increased substantially by reaming.
- Reaming produces highly finished surface.
- MRR is poor; MRR is not an issue in reaming.

Chapter - 10 Surface Finishing, Lapping :-

Definition of Surface Finish :-

→ Surface finishing is the process of altering the surface on an object like plating, polishing, anodizing, coating for the purpose of enhancing its appearance or functional properties.

→ The outermost boundary of a body adjacent to the air is called surface.

When sharp cutting edge, the term surface finish describe the boundary.

→ A Good surface is affected by many variables in single or multiple point machining.


Surface finish is defined in terms of 4 factors:-

Roughness :- Closely spaced surface irregularities, resulting from the manufacturing process or tools.

Lay :- The overall direction of the roughness pattern which can be affected by the machine and setup.

Waviness :- longer spaced irregularities caused

→ Broaching is a similar technique to shaping with a long multiple-tooth cutter.



(Broaching Operation)
Types of Broaching :-

Broaching's are two types :-

- (1) Pull type
- (2) Push type

Pull broaching :-

Workpiece is clamped to the broaching machine in stationary position and the broach is pulled through the work.

Broaches are usually long and are held in a special head. Pull broaching is mostly used for internal broaching.